## Waste Site Reclassification Form

<u> </u>			
Date Submitted; 8/27/1999	Operable Unit(s):	200-CW-5	Control Number: 99-067
Originator: 13.H. Ford	Waste Site ID:	UPR-200-W-139	j
Phone: 372-9176	Type of Reclassifica		
	Rejected Closed-Ou	<b>(</b>	·
	No Action	0	
This form documents agreement unit as rejected, closed-out, or nemoval from the NPL of no acti	o action and autho	rizing backfill of the site	e, if appropriate. Final
Description of current waste site cond	<del></del>		
The site is an unplanned release into the easter Currently, the eastern fork of the ditch is not a There are no permanent monuments or other is open, dry ditch. There is mature sagebrush gre	oarked or posted. It has no doutifiers at the site. The be	chain barricades or radiation wa rad and of the 216-U-9 Ditch, be	rning signs and it partially backfilled.
		DE	CIENTIVIEN.
			364 N 15
		. 44 A	PR 2 1 2000
			EDMC
Basis for reclassification; The site is fully contained in the 216-U-9 Ditch	n and will be addressed wit	h the cleanur of the 216-U-9 Dis	koh.
·			
	•		
	·		
BLYAN L. FOL	EY Signature	gu S. Fary	1/26/00 Date
Ecology Project Menager  Douglas R. Shet	Signature	<u> </u>	Dete
	. 11	$\mathcal{L}$	// . [] . / -/

## Waste Information Data System General Summary Report

11/23/1999

Site Code: UPI	1-200-W-138	Site Classification: Accepted	Page 1		
Site Names:	UPR-200-W-139, Liquid Rel	ease to the 216-U-9 Ditch, UN-200-W-139, UPR-20	0-W-18		
Bite Type:	Unplanned Release	Start Date:	1953		
Status:	Inactive	End Date:	1954		
Operable Unit:	200-CW-5	Coordinates:			
Hanford Area: 200W	200W	(E) 0			
		(N) O	•		
		Washington State Pt			
Site Description:	U-9 Ditch was abandoned in has no chain barricades or ra monuments or other identifier	see into the eastern fork of the 216-U-9 Ditch. The e 1954. Currently, the eastern fork of the ditch is not a distion werning signs and is partially backfilled. The s at the site. The head and of the 216-U-9 Ditch, beg th. There is mature sage brush growing on the side	narked or posted, it re are no permanent pinning south of 13th		
	This elte has been consolidate	ed with the 216-U-O Ditch.	÷		
Location Description:		-200-W-139 occurred within the eastern fork of the 216-U-9 Ditch. The ditch lies southwest of the SX Tank Farm, outside of the 200 West Area perimeter fence.			
Process Description:	fork of the 216-U-9 Ditch. The Ditch was released from rac	werflow from the 216-U-10 Pond. The release alte w e ditch connected the 216-U-10 Pond with the 216-S listion zone status in 1969. In 1973, a portion of the act the 216-U-10 Pond overflow to the 216-S-16 Pon al 216-U-9 Ditch were reused.	5-17 Pand. The 216-U- 216-U-9 Ditch was		
Associated Structures:	UPR-200-W-139 was associa	ated with the 216-U-9 Dijoh.			
Bite Comment:	was reported to have been de- aigns located at intervals on b provided. The release occurre and UPR-200-W-18 are both	nel 216-U-9 Ditch was covered in the Spring of 1954 signated as a radiation zone and posted with "Under oth sides of the ditch. Additional corrective action m ad in September 1953. Based on a document review the same event. In 1973, a new overflow ditch was a I-16 Pond. The new ditch is known as the 216-U-9 w	ground Contamination" ay have been y, UPR-200-W-139 opened between the		
Cleanup Activities:	from U Swemp (216-U-10) to bored at each end of the ditch detected. It was recommende trenches approximately 1.2 me	test holes were bored to a depth of 2.4 meters (6 feet) in the old ditch leading 1-10) to the old Reduction Oxidation (REDOX) Swamp (216-S-17). Holes were not the clitch and near the center of the length of the ditch. No contamination was nomended that the ditch be released from radiation zone status. In 1973, four y 1.2 meters (4 feet) deep were dug acrose the old ditch prior to installing a new is the 216-U-10 Pond and the 216-S-16 Pond. No contamination was found.			
teleans Jescription:	spring of 1954, the contaminal	n an unknown source was detected in the 216-U-9 Ditch in September 1953. In the contamination was covered with 0.6 meters (2 feet) of clean soil. It was designated and posted with Underground Radioactive Material signs. No mention is found in ing the level of contamination.			
invironmental Ionitoring Jescription:	the facility. No radioactivity wa	s were cut across the 216-U-9 Ditch at intervals to determine the radiation status of activity was found. When a new trench was cut from the 216-U-10 Pond to the 216-cuting used the first 153 meters (500 feet) of the original 216-U-9 Ditch. No cuntered in the digging.			
deferences;	1959, HW-60607. 2. H. L. Mexifield, 4/1/79, Hand 3. R. D. Stenner, K. H. Crame Waste Sites at Hanford, PNL-4. 4. 2/89, Preliminary Operable 5. Deford, D.H., R.W. Carpen	nconfined Underground Radioective Waste and Cor dbook - 200 Ares Waste Sites (Volumes 1, 2 and 3) rr, D. A. Lamer, 10/88, Hezard Ranking System Eve 8456 Vol 1,2,3. Units Designation Project, WHC-EP-0216, ter, 1995, 8-Plant Aggregate Ares Management Stu	, RHO-CD-673. Juntion of CERCLA inective		
	BHI-00176.	O WEST "S" PLANT FACILITIES, H-2-44510, Sht :			

6. KEY PLAN AREA MAP-200 WEST "S" PLANT FACILITIES, H-2-44510, SM 2.

Site Code: UPR-200-W-138 Site Classification: Accepted Page 2

Regulatory Information:

Programmatic Responsibility

**DOE Program:** 

EM-40

Confirmed By Program:

Yes

**DOE Division:** 

**RPD - Restoration Projects Division** 

Responsible

Contractor/Subcontractor:

BHI - Bechtel Hanford, Inc.

Site Evaluation

**Solid Waste Management Unit:** 

No

TPA Waste Management Unit Type:

**Unplanned Release Unit** 

This Site Was Consolidated With:

218-U-9, U Swamp-S Swamp Ditch, 218-U-6 Reason: Within Boundary Of Larger Site

**Permitting** 

RCRA Part A Permit:

216/218 Permit:

No

RCRA Part B Permit:

No

NPDES:

No

Closure Plan:

No

State Waste Discharge Permit:

No

**TSD Number:** 

Septic Permit:

No

Air Operating Permit: No

inert Landfill:

No

Air Operating Permit Number(s):

Tri-Party Agreement

Lead Regulatory Agency:

**EPA** 

**Unit Category:** 

**CERCLA Past Practice (CPP)** 

TPA Appendix:

C

Remediation and Closure

**Decision Document:** 

**Decision Document Status: Remediation Design Group:** 

**Closure Document:** 

Closure Type:

**Post Closure Requirements:** 

Residual Waste:

Waste Information:

Type:

**Process Effluent** 

Category:

Mbood Liquid

Description:

Physical State:

References state the ditch became contaminated in September of 1953 and was backfilled in

spring of 1954. No details of the release are included.

References:

1. K. F. Baldridge, 7/15/59, Unconfined Underground Radioactive Waste and Contamination in the 200

Areas - 1959, HW-60807.

2. R. D. Stenner, K. H. Cramer, D. A. Lamar, 10/88, Hazard Ranking System Evaluation of CERCLA

Inactive Waste Sites at Hanford, PNL-6456 Vol 1,2,3.

Site Code: UPR-200-W-138 Site Classification: Accepted Page 3

Field Work:

Type:

Site Walkdown

Begin Date:

07/30/1999

Field Crew;

C. R. Webb

End Date:

07/30/1999

Purpose:

verification

Comment:

The release is not separately marked or posted from the ditch.

References:

1. C. R. Webb, Field Logbook assigned to Christine Webb, EL-1255 and EL-1255-1.

<u>lmages:</u>

Date Taken:

3/10/98

Pathname:

\bhi002\eed-img\200\\\1449\1449\_01.JPG

Description:

This digital photo was taken at the north and of 216-U-9 looking south. 216-U-9 was the alts of

this unplanned release.

Date Taken:

7/30/99

Pathname:

\bhi002\eed-img\200W\1449\1449\_02.JPG

Description:

Photo shows the dry 216-U-9 ditch looking south.